



x 1



x 1




2

M6


x

70

x 2



x 1




3

M6


x

50

x 2



x 1




4

M6



x

14


x 2




6



6



x 1




1

M6

x

100

x 1




9

M6

x

15

x 2




10

M6

x

45

x 2





4

M6


x

14

x 1



x 1



5

M4



x

25

x 3

TOOLS REQUIRED (NOT PROVIDED)

Phillips Screwdriver




6

M6

x

15

x 1




8

SET

x 2

SET x 2



1

M6
x
100



x 1

A



x 1

2

M6
x
70



x 2

B



x 1

3

M6
x
50



x 2

C



x 1

4

M6
x
14



x 3

D



x 1

5

M4
x
25



x 3

E



x 1

6



x 2

F



x 1

7



x 1

9

M6
x
15



x 2

10

M6
x
45



x 2

8



SET x 2