



JIKAWO



A warning icon showing a crossed-out drill bit.

A warning icon showing a triangle with an exclamation mark.


A warning icon showing a lightning bolt inside a circle.

A warning icon showing a triangle with an exclamation mark.

A clock icon indicating a 10-minute assembly time.
10'A person icon indicating that 1 person is required for assembly.
1

1/4


2099/JIKAWO/200224/



A x 1	B x 1	C x 1
----------	----------	----------

2/4

2099/JIKAWO/200224/



1

A x 1	B x 1	C x 1
----------	----------	----------

3/4

2099/JIKAWO/200224/

2

