



CORBONES



A warning icon showing a power drill with a diagonal line through it, indicating that power tools should not be used for assembly.

A warning icon showing a lightning bolt inside a circle, indicating high voltage.

A warning icon showing a triangle with an exclamation mark, indicating sharp edges.



A clock icon with the text "5'", indicating the assembly time is 5 minutes.

A simple icon of a person, indicating the number of people required for assembly.

1

1/3

552/CORBONES/220825/



1

A diagram showing the first step of assembly. A rectangular box contains a drawing of the lamp's pole with a label 'A' and 'x 1'. Below the box, a series of three circular diagrams show the pole being inserted into the base. The first circle is labeled '1' and the second is labeled '2'. The pole is labeled 'A'.

A diagram showing the first step of assembly. A rectangular box contains a drawing of the lamp's pole with a label 'A' and 'x 1'. Below the box, a series of three circular diagrams show the pole being inserted into the base. The first circle is labeled '1' and the second is labeled '2'. The pole is labeled 'A'.

2

A diagram showing the second step of assembly. A rectangular box contains a drawing of the lamp's pole with a label 'A' and 'x 1'. Below the box, a series of three circular diagrams show the lamp head being attached to the pole. The first circle is labeled '1' and the second is labeled '2'. The lamp head is labeled 'A'.