


# ANTRIA









Diagram illustrating assembly instructions and safety warnings:

- Warning 1:** A warning triangle with an exclamation mark is positioned above a box containing an L-shaped metal bracket and a power drill with a slash through it, indicating that a power drill should not be used for this step.
- Warning 2:** A second warning triangle with an exclamation mark is positioned above a box containing a rectangular block being placed on a textured surface and a diagram showing the block being secured with a screw.
- Time:** A clock icon with a circular arrow indicates a 20-minute assembly time.
- Personnel:** An icon of a person indicates that 2 people are required for assembly.




1 x 2

1



x 1

3




x 1

A





x 2

C




x 1




2 x 2

4




x 1

A





x 2




C






x 1



3 x 2




4 x 2




5 x 2

6



x 1

6



6 x 2

5



x 1

5

