



CALVILLO



A warning icon showing a power drill with a diagonal line through it, indicating that power tools should not be used for assembly.

A warning icon showing a lightning bolt inside a circle, indicating high voltage.


A warning icon showing a triangle with an exclamation mark, indicating sharp edges.

A clock icon with the text "15'" next to it, indicating that the assembly should take approximately 15 minutes.

A simple icon of a person, indicating that one person is required for assembly.

1/4

2185/CALVILLO/070324/



A x 1	B x 1	C x 1	D x 1
----------	----------	----------	----------

1

A
x 1

1

2



2

B
x 1

1

2

3



4

