




x 1



x 1




M6

x

70

x 2



x 1




M6


x

50

x 2



x 1




M6



x

14


x 2




6



6



x 1




M6

x

100

x 1




M6

x

15

x 2




M6

x

45

x 2





M6


x

14

x 1



x 1



M4





x

25

x 3

TOOLS REQUIRED (NOT PROVIDED)

Phillips Screwdriver




M6

x

15

x 2




M6

x

45

x 2



M6

x

14

x 1



M6

x

15

x 2



M6

x

45

x 2





M6

x

14

x 1

51090		PAGE 1/5			
		1	M6 x 100  x 1		
A	 x 1	2	M6 x 70  x 2		
B	 x 1	3	M6 x 50  x 2		
C	 x 1	4	M6 x 14  x 3		
D	 x 1	5	M4 x 25  x 3		
E	 x 1	6	 x 2		
F	 x 1	7	 x 1		
9	M6 x 15  x 2	10	M6 x 45  x 2	8	 SET x 2