











1/9





2/9

678/TESERO/20062018/

 x 2	 x 2	 x 1
 x 1	 x 2	 x 2
 x 1	 x 2	 x 2
 x 1	 x 2	 x 4

3/9



678/TESERO/20062018/

P2  M8 x 58 x 6	P3  M8 x 80 x 6	P4  M6 x 62 x 4	
T  x 4	T1  x 10	S1  x 10	
N1  x 10	S  x 4	N  x 4	V  x 1
X  x 2	Y  x 4	Z1  M8 x 1	Z2  M6 x 1

4/9

1 x 2

A x 1	B x 1	G x 1	T1 x 2	P2 M8 x 58 x 1
P3 M8 x 80 x 1	S1 x 2	N1 x 2	V x 1	Z1 M8 x 1




5/9

678/TESERO/20062018/


2

C x 1	P2 M8 x 58 x 2	T1 x 2	S1 x 2	N1 x 2	V x 1	Z1 M8 x 1
----------	-------------------------	-----------	-----------	-----------	----------	-----------------



3



E x 1	P3 M8 x 80 x 4	T1 x 4	S1 x 4	N1 x 4	V x 1	Z1 M8 x 1
----------	-------------------------	-----------	-----------	-----------	----------	-----------------



6/9

4


F  x 2	K  x 1	O  x 4	P4  M6 x 62 x 4	
T  x 4	P  x 4	N  x 4	V  x 1	Z2  M6 x 1



7/9


5

M x 2



6

I x 2	J x 2
----------	----------





8/9



678/TESERO/20062018/

7

P2  M8 x 58 x 2	X  x 2	Y  x 4	Z1  M8 x 1
--	---	---	---



8



9/9