









GOSHAABA








A




x 1

B




x 1

C




x 1

D



x 1

E



x 1

F




x 1

G




x 1

H




x 1

I




x 5

J



x 1

K




x 1

L




x 1

M



x 2

N



x 4

O



x 15

P






x 1

Q



x 2

		 3CCT 3000K 4200K 6000K
		CRI ≥ 80  MOTOR AC
 Máx. 13°	 $2,3\text{m} < h < 2,7\text{m}$	 $20\text{m}^2 < S < 30\text{m}^2$



A




x 1




M



x 2



OFF



A





x 1

N



x 4





E









x 1






F






x 1





1



2




3



4

I





x 5

O



x 15






5

J




x 1




6


K




x 1



1a



1b





7

L




x 1







8





B



x 1



9



!

P




x 1


Q




x 2




1a



1b



2b



2a

