


MARICAO






Diagram illustrating the required tools and safety warnings for the installation step.


Tools: A screwdriver and a power drill are shown as the required tools for this step.

Warnings: Two warning symbols are present: a triangle with an exclamation mark (general warning) and a triangle with a lightning bolt (electrical warning).


Duration: The estimated time for this step is 15 minutes, indicated by a clock icon.




Personnel: The step requires 1 person, indicated by a person icon.

1/4








B x 3







<p>A</p>  <p>x 1</p>	<p>B</p>  <p>x 3</p>	<p>C</p>  <p>x 2</p>	<p>D</p>  <p>x 2</p>
---	---	---	---

1



2



3

